

NAVICPEA01

(NOV 1992)

SOURCE INSPECTION & ACCEPTANCE LEVEL1/SUBSAFE MATERIALS

Supplies and Services to be provided hereunder will be inspected at contractor's plant. LEVEL 1/SUBSAFE Certifying Activity will jointly, at source, with the cognizant Quality Assurance Representative (QAR) from the Defense Contract Management Command inspect, certify, accept, and release this material from the contractor's plant.

The contractor shall provide a minimum of seven (7) Government working days advance notice to the QAR when material will be ready for acceptance inspection. In the case of materials for oxygen/nitrogen service or for other items with internals requiring certification, the contractor shall provide a minimum of seven (7) Government working days advance notice to the DCMC-QAR when material will be ready for acceptance prior to cleaning or assembly.

When the contract does not allow vibro-etch type markings, the contractor is required to make available for use by the Government's joint inspection/certification team appropriate marking equipment and/or personnel to facilitate final certification marking.

Applicable certifying activity and point of contact will be provided to the DC MC-QAR by separate correspondence.

RETURN TO INDEX.